

L Number	Hits	Search Text	DB	Time stamp
-	1361	repair\$3 ADJ defect	USPAT; EPO; JPO	2001/10/16 14:15
-	29385	display with pixel	USPAT; EPO; JPO	2001/10/16 14:04
-	44	(repair\$3 ADJ defect) and (display with pixel)	USPAT; EPO; JPO	2001/10/17 15:06
-	713	repair\$3 and (display with pixel)	USPAT; EPO; JPO	2001/10/16 14:33
-	337	(repair\$3 and (display with pixel)) and laser	USPAT; EPO; JPO	2001/10/16 14:16
-	34	((repair\$3 ADJ defect) and (display with pixel)) and laser	USPAT; EPO; JPO	2001/10/16 14:41
-	1	(repair\$3 or correct\$3) ADJ (display with pixel)	USPAT; EPO; JPO	2001/10/16 14:41
-	9083	(repair\$3 or correct\$3) and (display with pixel)	USPAT; EPO; JPO	2001/10/17 15:05
-	2099	((repair\$3 or correct\$3) and (display with pixel)) and laser	USPAT; EPO; JPO	2001/10/16 15:45
-	125	349/192	USPAT; EPO; JPO	2001/10/16 14:48
-	57	349/192 and laser	USPAT; EPO; JPO	2001/10/17 14:56
-	145	((repair\$3 or correct\$3) and (display with pixel)) and short ADJ circuit	USPAT; EPO; JPO	2001/10/16 15:45
-	113	(repair\$3 or correct\$3) ADJ short ADJ circuit	USPAT; EPO; JPO	2001/10/16 16:32
-	19	(display with pixel) and ((repair\$3 or correct\$3) ADJ short ADJ circuit)	USPAT; EPO; JPO	2001/10/16 16:33
-	2	349/192 and ((repair\$3 or correct\$3) ADJ short ADJ circuit)	USPAT; EPO; JPO	2001/10/16 16:33
-	15	((display with pixel) and ((repair\$3 or correct\$3) ADJ short ADJ circuit)) and laser	USPAT; EPO; JPO	2001/10/16 16:33
-	192	stack\$3 ADJ conduct\$3 ADJ (layer or film)	USPAT; EPO; JPO	2001/10/17 14:58
-	36	(stack\$3 ADJ conduct\$3 ADJ (layer or film)) with insulat\$3 ADJ layer	USPAT; EPO; JPO	2001/10/17 15:01
-	5	(repair\$3 or correct\$3) and ((stack\$3 ADJ conduct\$3 ADJ (layer or film)) with insulat\$3 ADJ layer)	USPAT; EPO; JPO	2001/10/17 15:03
-	23	(repair\$3 or correct\$3) and (stack\$3 ADJ conduct\$3 ADJ (layer or film))	USPAT; EPO; JPO	2001/10/17 15:01
-	1204	(repair\$3 or correct\$3) with short ADJ circuit	USPAT; EPO; JPO	2001/10/17 15:32
-	60	((repair\$3 or correct\$3) with short ADJ circuit) and (display with pixel)	USPAT; EPO; JPO	2001/10/17 15:35
-	0	(repair\$3 or correct\$3) with remov\$3 ADJ conducti\$3 ADJ layer	USPAT; EPO; JPO	2001/10/17 15:33
-	1	(repair\$3 or correct\$3) with remov\$3 ADJ conducti\$3 ADJ layer	USPAT; EPO; JPO	2001/10/17 15:34
-	57	(repair\$3 or correct\$3) and remov\$3 ADJ conducti\$3 ADJ layer	USPAT; EPO; JPO	2001/10/17 15:38

	2	((repair\$3 or correct\$3) and remov\$3 ADJ conducti\$3 ADJ layer) and (display with pixel)	USPAT; EPO; JPO	2001/10/17 15:39
	432	(repair\$3 or correct\$3) and remov\$3 ADJ conducti\$3	USPAT; EPO; JPO	2001/10/17 15:50
	19	((repair\$3 or correct\$3) and remov\$3 ADJ conducti\$3) and (display with pixel)	USPAT; EPO; JPO	2001/10/17 16:07
	9	(((repair\$3 or correct\$3) and remov\$3 ADJ conducti\$3) and (display with pixel)) and laser	USPAT; EPO; JPO	2001/10/17 16:46
	5	(repair\$3 or correct\$3) and (inter ADJ (layer or fiim) ADJ short ADJ circuit)	USPAT; EPO; JPO	2001/10/17 20:00
	31	(repair\$3 or correct\$3) and ((layer or fiim) ADJ short ADJ circuit)	USPAT; EPO; JPO	2001/10/17 16:06
	1	((repair\$3 or correct\$3) and ((layer or fiim) ADJ short ADJ circuit)) and (display with pixel)	USPAT; EPO; JPO	2001/10/17 20:13
	15	((repair\$3 or correct\$3) and ((layer or fiim) ADJ short ADJ circuit)) and laser	USPAT; EPO; JPO	2001/10/17 16:10
	5903	(repair\$3 or correct\$3) with auxiliary	USPAT; EPO; JPO	2001/10/17 20:22
	1327	((repair\$3 or correct\$3) with auxiliary) and terminal	USPAT; EPO; JPO	2001/10/17 20:23
	7	(((repair\$3 or correct\$3) with auxiliary) and terminal) and insulat\$3 ADJ (film and layer)	USPAT; EPO; JPO	2001/10/17 20:04
	394	(((repair\$3 or correct\$3) with auxiliary) and terminal) and display	USPAT; EPO; JPO	2001/10/17 20:06
	0	(((repair\$3 or correct\$3) with auxiliary) and terminal) and display) and extract\$3 ADJ wir\$3	USPAT; EPO; JPO	2001/10/17 20:06
	0	(((repair\$3 or correct\$3) with auxiliary) and terminal) and display) and above ADJ extract\$3	USPAT; EPO; JPO	2001/10/17 20:06
	0	(((repair\$3 or correct\$3) with auxiliary) and terminal) and display) and above ADJ extract\$3	USPAT; EPO; JPO	2001/10/17 20:07
	0	(((repair\$3 or correct\$3) with auxiliary) and terminal) and display) and (above and (under or below)) ADJ wir\$3	USPAT; EPO; JPO	2001/10/17 20:09
	304	(((repair\$3 or correct\$3) with auxiliary) and terminal) and display) and (above and (under or below))	USPAT; EPO; JPO	2001/10/17 20:24
	215	((repair\$3 or correct\$3) with auxiliary) and connect\$3 ADJ terminal	USPAT; EPO; JPO	2001/10/17 20:24
	9365	"32" and bus ADJ line	USPAT; EPO; JPO	2001/10/17 20:11
	12	(((repair\$3 or correct\$3) with auxiliary) and connect\$3 ADJ terminal) and bus ADJ line	USPAT; EPO; JPO	2001/10/17 20:52
	5	(((repair\$3 or correct\$3) with auxiliary) and connect\$3 ADJ terminal) and (display with pixel)	USPAT; EPO; JPO	2001/10/17 20:17
	34	(((repair\$3 or correct\$3) with auxiliary) and terminal) and (display with pixel)	USPAT; EPO; JPO	2001/10/17 20:23

	82337	(repair\$3 or correct\$3) with (auxiliary (line or wir\$3))	USPAT;	2001/10/17
	1710	((repair\$3 or correct\$3) with (auxiliary (line or wir\$3))) and (display with pixel)	EPO; JPO	20:44
	648	(((repair\$3 or correct\$3) with (auxiliary (line or wir\$3))) and (display with pixel)) and terminal	USPAT;	2001/10/17
	553	((((repair\$3 or correct\$3) with (auxiliary (line or wir\$3))) and (display with pixel)) and terminal) and (above and (under or below))	EPO; JPO	20:46
	59	((((repair\$3 or correct\$3) with (auxiliary (line or wir\$3))) and (display with pixel)) and terminal) and connect\$3 ADJ terminal	USPAT;	2001/10/17
	6072	(repair\$3 or correct\$3) with (auxiliary (line or wir\$3) with insulat\$3 ADJ (layer or film))	EPO; JPO	20:23
	141	((repair\$3 or correct\$3) with (auxiliary (line or wir\$3) with insulat\$3 ADJ (layer or film))) and (display with pixel)	USPAT;	2001/10/17
	226	((repair\$3 or correct\$3) with (auxiliary (line or wir\$3) with insulat\$3 ADJ (layer or film))) and connect\$3 ADJ terminal	EPO; JPO	20:49
	5903	(repair\$3 or correct\$3) with (auxiliary (line or wir\$3) ADJ (above and under) ADJ insulat\$3 ADJ (layer or film))	USPAT;	2001/10/17
	111	((repair\$3 or correct\$3) with (auxiliary (line or wir\$3) ADJ (above and under) ADJ insulat\$3 ADJ (layer or film))) and (display with pixel)	EPO; JPO	20:51
	5	(((repair\$3 or correct\$3) with (auxiliary (line or wir\$3) ADJ (above and under) ADJ insulat\$3 ADJ (layer or film))) and (display with pixel)) and bus ADJ line	USPAT;	2001/10/17
	102	(((repair\$3 or correct\$3) with (auxiliary (line or wir\$3) ADJ (above and under) ADJ insulat\$3 ADJ (layer or film))) and (display with pixel)) and line	EPO; JPO	20:52
	56	(((repair\$3 or correct\$3) with (auxiliary (line or wir\$3) ADJ (above and under) ADJ insulat\$3 ADJ (layer or film))) and (display with pixel)) and (signal or scanning) ADJ line	USPAT;	2001/10/17
	47	(((repair\$3 or correct\$3) with (auxiliary (line or wir\$3) ADJ (above and under) ADJ insulat\$3 ADJ (layer or film))) and (display with pixel)) and line) and liquid ADJ crystal	EPO; JPO	21:10
				20:56
				21:11